Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EDR ID Number

BF281 NYNEX MANHOLE-CROSSBAY BL NY Spills S102662587 WNW CROSSBAY BLVD/BAY 53RD ST N/A

1/4-1/2 BROOKLYN, NY

0.414 mi.

2184 ft. Site 1 of 8 in cluster BF

 Relative:
 SPILLS:

 Higher
 Name:
 NYNEX MANHOLE-CROSSBAY BL

 Actual:
 Address:
 CROSSBAY BLVD/BAY 53RD ST

 11 ft.
 City,State,Zip:
 BROOKLYN, NY

 City, State, Zip:
 BROOKLYN, NY

 Spill Number/Closed Date:
 9407139 / 1995-03-06

 Facility ID:
 9407139

Facility Type: ER DER Facility ID: 258518 320894 Site ID: DEC Region: 2 Spill Cause: Unknown Spill Class: C4 2401 SWIS: Spill Date: 1994-08-26 Investigator: **MCTIBBE** Referred To: Not reported Reported to Dept: 1994-08-26 CID: Not reported Water Affected: Not reported Spill Source: Unknown Spill Notifier: Other Cleanup Ceased: Not reported Cleanup Meets Std: False Last Inspection: Not reported Recommended Penalty: False **UST Trust**: False Remediation Phase:

Remediation Phase:

Date Entered In Computer:

Spill Record Last Update:

Spiller Name:

Spiller Company:

UNKNOWN

Spiller Address:

O
1994-10-21
1997-08-13
Not reported
UNKNOWN

Not reported

Spiller Company: 999

Contact Name: TIM MCCLOSTON

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was

TIBBE CLEANED BY NYNEX. "

Remarks: "VAC TRUCK WILL BE USED"

All Materials:

 Site ID:
 320894

 Operable Unit ID:
 1004572

 Operable Unit:
 01

 Material ID:
 380154

 Material Code:
 0066A

Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: L
Recovered: .00

Oxygenate: Not reported